



*co/c*  
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re the application of

DENNIS SCHULTZ

Patent No.: 6,969,221 B2

Issued: November 29, 2005

Serial No: 10/716,569

Filed: November 18, 2003

For: THREADED INSERT FOR  
FASTENERS

Examiner: Neill Wilson

Group Art Unit: 3676

Client ID/Matter No: HISHE 66269

March 10, 2006

Los Angeles, California 90045

REQUEST FOR CERTIFICATE OF CORRECTION  
FOR APPLICANT'S MISTAKE

**Certificate**

**MAR 31 2006**

**of Correction**

Certificate of Correction Department  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Dear Sir:

It is noted that an error appears in the above-identified patent of a clerical nature, as more fully described below.

ERROR

Column 1, Line 42, after "the external" insert --surface of the threaded insert. The depth of the dovetail slot is typically greater than the depth of the male threads on the external surface of the threaded insert.--.

This error occurred in good faith. Since correction thereof does not involve such change in the patent as would constitute new matter or would require re-examination, it is requested that this Certificate of Correction be issued and returned to us. Attached is a check in the amount of \$100.00 to cover the necessary fees. If any additional fees are needed, please charge Deposit Account No. 06-2425.

Attached hereto, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.

A duplicate of this document is attached.

Respectfully submitted,

FULWIDER PATTON LLP

By: \_\_\_\_\_  
James W. Paul  
Registration No. 29,967

JWP:ck  
Enclosure

Howard Hughes Center  
6060 Center Drive, Tenth Floor  
Los Angeles, CA 90045  
Telephone: (310) 824-5555  
Facsimile: (310) 824-9696  
Customer No. 24201

118484

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,969,221 B2

APPLICATION NO.: 10/716,569

ISSUE DATE : November 29, 2005

INVENTOR(S) : Dennis Schultz

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 42, after "the external" insert --surface of the threaded insert. The depth of the dovetail slot is typically greater than the depth of the male threads on the external surface of the threaded insert.--.

## MAILING ADDRESS OF SENDER:

**James W. Paul  
Fulwider Patton LLP  
6060 Center Drive, 10<sup>th</sup> Floor  
Los Angeles, CA 90045**

This collection of information is required by 37 CFR 1.322 and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing the burden, should be sent to the Chief of Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450 Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORM TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner of Patents P.O. Box 1450 Alexandria, VA 22313-1450